

RECEIVING INSPECTION REPORT  
Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080162-4  
2961 E. COLORADO ST., PASADENA, CALIF.

RECEIVED FROM

DATE REC'D 5-57  
P.O. NO. 654

VENDOR PACKING SLIP NO. 5874

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO.	S.O. NO.	
	DRAWING NO. AND DESCRIPTION											
4	322	00000	106	0	23							
	730126-26 Relay Time Delay 3 Sec., 3V MFG-01-NO-28											
	QUANTITY											
	ACCEPTED											
	REJECTED											
	REMARKS											
	4											
	to store											

RECEIVED BY *J. Barajas* INSPECTED BY *RPE* DATE 4-6-57 REJECTS RETURNED ON SHIP MEMO NO.

RECEIVING INSPECTION REPORT  
HYCON MFG. COMPANY  
2961 E. COLORADO ST., PASADENA, CALIF.

No. 11817

RECEIVED FROM

DATE REC'D 5-57  
P.O. NO. 654

VENDOR PACKING SLIP NO. 5874

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO.	S.O. NO.	
	DRAWING NO. AND DESCRIPTION											
16	322	00000	NOTED									
	730126-121 AM Connector, 4031021-20-075 (322-00000-118-3-23-1)											
	QUANTITY											
	ACCEPTED											
	REJECTED											
	REMARKS											
	16											
	to store											

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080162-4

RECEIVED BY *J. Barajas* INSPECTED BY *RPE* DATE 4-5-57 REJECTS RETURNED